

Balle "Desktop" Computer

Kiwon lafiya da Kariya



Sanya Kayan Kariyanka¹



Kar Ka gwada kaya-kan ka soma ballewa²



Ka wanke hanuwanka bayan aiki gabarin ko wani hutawa



Ka bar wurin ka ya kasance cikin tsabta



Mataki 1
Cire "screw" ka kuma fitar da "Case" gidan



Mataki 2
Hade ka kuma fitar da duk wayayi



Mataki 3
Fitar a duk "drives" da "mainboard" da kuma Sashin dake bada wuta



Mataki 4
Fitar da babban bangaren "aluminium" daga "mainboard"³



Mataki 5
Kwance "screw printed wiring board" daga "hard disc drive"



Mataki 6
Bude "hard disc drive".⁴ Don yawancin "hard disc drives" ana bukatar "Torx screwdrivers" na musanman. Yawanci, "Torx-Size 9" ake bukata



Mataki 7
Yi anfani da "screedriver" ka cire "magnet units" akan "magnetic force" su



Mataki 8
Fitar da "copper coil" ka duba "hard disc drive" da aka cire Zuwa "(a) aluminium, (b) printed wiring board, (c) magnets" da takalminkarfe, "(d) copper and (e) screws"⁵



Mataki 9
Balle "CD/DVD drive" ka nemi kayan citin "wiring boards, steel" karafa da "plastic"



Mataki 10
Balle "Power Supply Unit"



Mataki 11
Cire babbar "aluminium" da bangaren "Steel/Copper" daga "printed circuit board" na rabon wuta⁶



Mataki 12
Rarabe duk kayan da aka balle cikin (a) roba "plastics", (b) karafa, "ferrous metals", (c) "printed wiring board", (d) "aluminium", (e) wayoyi, "cables" (f) "mixed materials", (g) rare earth magnets⁷



Mataki 13
Balle "CD/DVD drive" ka nemi kayan citin "wiring boards, steel" karafa da "plastic"



Mataki 14
Balle "Power Supply Unit"



Mataki 15
Cire babbar "aluminium" da bangaren "Steel/Copper" daga "printed circuit board" na rabon wuta⁶



Mataki 16
Rarabe duk kayan da aka balle cikin (a) roba "plastics", (b) karafa, "ferrous metals", (c) "printed wiring board", (d) "aluminium", (e) wayoyi, "cables" (f) "mixed materials", (g) rare earth magnets⁷

Further information: www.resourcefever.org

¹ Dogoon rigan aiki, takalmink alki me kariya, "gloves" wato safaran aiki, abin kare nanci. Diga kura da madabin ido wato tabarau me kariya.

² Sawaa ciki da kuma gwadawa zai iya calin "capacitors" abindia zai ya lawo barna na bugawan lantakai lokacin da ske lokarin cirewa.

³ Wasu masu sake sarrafa na fitar da "processor" da "RAMs" su soyar a matsayin bangare ware.

⁴ Mataki na 6-11 kuma zasya zama kafa zuwa mayyan lantakan kwaratu.

⁵ Case da "platters" diuk "aluminium" ne don haka basu ballewa. "Yayin" da wasu marafa "aluminium" ne, Saure kuwa daga karafa ne da basu lankwasu.

⁶ "transformers, heatsinks" da manya "plastic" roboti da sauran karafa (rege grima da yawa) hadadun karafa (magnets) (shine) "demagnetisation" da roba bangorin karafa)

⁷ Kain sarrada da ake bukata wa "plastic" roboti da sauran karafa (rege grima da yawa) hadadun karafa (magnets) (shine) "demagnetisation" da roba bangorin karafa)